PRINT DATE: 01/13/94

PAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE

NUMBER: M7-3A-E4-X

SUBSYSTEM NAME: TUNNEL ADAPTER - ECLSS

REVISION : 0 01/13/94 W

PART NAME VENDOR NAME PART NUMBER VENDOR NUMBER

LRU :

EQUALIZATION VALVE CARLETON TECHNOLOGIES MC250-0004-0012

2763-0001-9

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: EQUALIZATION VALVE, TUNNEL ADAPTER/SPACELAB HATCH "D".

QUANTITY OF LIKE ITEMS: 2 TWO ON HATCH "D"

FUNCTION:

PROVIDES PRESSURE EQUALIZATION ACROSS THE TUNNEL ADAPTER AND SPACELAB HATCH. EACH VALVE OPERATES INDEPENDENTLY WITH POSITIVE DETENTS AT TWO FLOW POSITIONS. VALVE CAN BE ACTUATED FROM EITHER SIDE OF HATCH.

2

PRINT DATE: 01/13/94

ILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE NUMBER: M7-32-E4-02

REVISION: 0 01/13/94 W

SUBSYSTEM: TUNNEL ADAPTER - ECLSS

LRU EQUALIZATION VALVE

CRITICALITY OF THIS ITEM NAME: EQUALIZATION VALVE FAILURE MODE: 1R2

FAILURE HODE:

INABILITY TO CLOSE, INTERNAL LEAKAGE

MISSION PEASE:

00 ON-CRBIT

VEHICLE/FAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA

: 103 DISCOVERY : 104 ATLANTIS : 105 ENDEAVOUR

CAUSE

CONTAMINATION, PHYSICAL BINDING/JAMMING, CORROSION, VIBRATION, MECHANICAL SHOCK, POROSITY.

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

- PAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF PRIMARY SEAL OF ONE EQUALIZATION VALVE.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT - CAP PROVIDES REDUNDANT SEAL.

(C) MISSION:

NO EFFECT.

(D) CREW, VEHICLE, AND ELEMENT(S):

PRINT DATE: 01/13/94

PAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE NUMBER: M7-3A-E4-02

NO EFFECT.

(E) FUNCTIONAL CRITICALITY EFFECTS:
SECOND ASSOCIATED FAILURE (INABILITY TO MATE EQUALIZATION VALVE CAP)
MAY RESULT IN LOSS OF EVA CREWMAN IF CONTINGENCY EVA IS REQUIRED AND
TUNNEL ADAPTER CANNOT BE REPRESSURIZED FOR RETURN TO CABIN (EVA CREWMAN
MUST REMAIN IN AIRLOCK UNTIL LANDING).

- DISPOSITION RATIONALE -

(A) DESIGN:

UNIT IS A BUTTERFLY VALVE WITH SILICONE ELASTOMER MOLDED IN PLACE ON THE VALVE, THUS ASSURING A CONTINUOUS UNBROKEN GAS SEAL ACROSS THE EDGE OF THE BUTTERFLY VALVE PREVENTING INTERNAL LEAKAGE. VALVE BORE IS HARD ANODIZED WITH TEFLON IMPREGNATED TO PROVIDE MAXIMUM CORROSION RESISTANCE WITH MINIMUM COEFFICIENT OF FRICTION.

UNIT IS FLANGE MOUNTED WITH A SINGLE SILASTIC-675 SILICONE RUBBER O-RING WHICH COMPENSATES FOR ROUGHNESS OF FLANGE, PREVENTING EXTERNAL LEAKAGE. HOUSING IS FABRICATED OF A356.0-T61 ALUMINUM ALLOY AND IS X-RAYED TO DETECT CRACKS.

(B) TEST:

QUALIFICATION TEST FOR 100 MISSION LIPE: ACCELERATION OF 5 G FOR FIVE MINUTES PER AXIS. SINUSOIDAL VIBRATION - 5 TO 35 HZ AT +/- 0.25 G PEAK PER AXIS. RANDOM VIBRATION - 0.09 G**2/HZ FOR 48 MIN/AXIS. DESIGN SHOCK- 20G PER AXIS. THERMAL VACUUM/THERMAL CYCLE - WITH VALVE CLOSED AND COVER ON, UNIT EXPOSED TO 120 TO 130 F AND VACUUM OF 1 X 10 EXP -6 TORR FOR 24 HOURS. LOW/HIGH TEMPERATURE CYCLE - HELD AT -40 TO -50 F FOR 3 HOURS AND AT +120 TO 130 F FOR 3 HOURS. OPERATING LIFE - OPERATED IN OFF/NORMAL/EMERGENCY POSITIONS WITH 15 PSIG APPLIED FOR 800 CYCLES. LEAKAGE MONITORED DURING OR AFTER THESE TESTS LIMITED TO 5 SCCM MAX. BURST PRESSURE TEST AT 30 PSIG (TWICE OPERATING PRESSURE) FOR 5 MINUTES.

ACCEPTANCE TEST - PROOF PRESSURE 25 PSIG GN2, WITH VALVE OPEN AND CLOSED. LEAK CHECK AT 15 PSIG, 5 SCCM MAX - VALVE OPEN AND CLOSED AND REVERSE LEAKAGE.

OMRSD - TUNNEL ADAPTER VALVES OPENING AND CLOSING TORQUES ARE VERIFIED WHEN TUNNEL ADAPTER IS INSTALLED. INTERNAL LEAK TESTED AT 13-15 PSIG, 25 SCCN MAX LEAKAGE, 3.2 PSID LEAK CHECK PERFORMED AT OPP AFTER TUNNEL ADAPTER INSTALLATION. GROSS LEAKAGE TEST AT 2 PSID BEFORE EACH FLIGHT.

(C) INSPECTION:

RECEIVING INSPECTION

MATERIALS VERIFIED AT RECEIVING INSPECTION. ALUMINUM HOUSING CASTINGS ARE HYDROSTATIC PROOF PRESSURE TESTED AT 32 PSID.

PRINT DATE: 01/13/94

4

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE NUMBER: M7-3A-E4-02

CONTAMINATION CONTROL CORROSION PROTECTION PROVISIONS AND CONTAMINATION CONTROL PLAN VERIFIED BY INSPECTION. CLEANLINESS LEVELS OF 200A AND 100 ML RINSE TESTS VERIFIED.

ASSEMBLY/INSTALLATION

MANUFACTURING PROCESSES, INSTALLATION AND ASSEMBLY VERIFIED BY INSPECTION. TORQUES VERIFIED BY INSPECTION. DIMENSIONAL CHECKS PERFORMED BY INSPECTION. INSPECTION PERFORMS MIPS FOR CONCENTRICITY AND PERPENDICULARITY. O-RINGS VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

ALUMINUM HOUSING CASTINGS ARE X-RAYED AND DYE PENETRANT INSPECTED TO DETECT CRACKS, VERIPIED BY INSPECTION.

CRITICAL PROCESSES

PASSIVATED PARTS AND HEAT TREATMENT VERIFIED BY INSPECTION. MECHANICAL SOLDERING OF DEBRIS SCREEN VERIFIED BY INSPECTION. ANODIZATION OF ALUMINUM PARTS VERIFIED BY INSPECTION.

TESTING

ATP VERIFIED BY INSPECTION.

HANDLING/PACKAGING

PARTS PROTECTION VERIFIED BY INSPECTION.

(D) FAILURE HISTORY:

(AC2285) DURING LEAK CHECK AFTER INSTALLATION OF HATCH "B" INTO VEHICLE, SUPER KOROPON PAINT CHIPS IN THE VALVE CAUSED INTERNAL LEAKAGE. VALVE WAS REMOVED FROM VEHICLE AND REPLACED. CONTAMINATED VALVE WAS RETURNED TO SUPPLIER, CLEANED AND RETURNED TO STOCK.

(E) OPERATIONAL USE:

NO CREW ACTION REQUIRED IF CAP IS INSTALLED. IF CAP IS NOT INSTALLED, CREW SHOULD INSTALL CAP AND USE REDUNDANT EQUALIZATION VALVE.

- APPROVALS -

EDITORIALLY APPROVED : RI EDITORIALLY APPROVED : JSC TECHNICAL APPROVAL : VIA CR